BASIC TROUBLESHOOTING FLOW CHART

STEPS ALREADY TAKEN BEFORE PLUGGIN IN:
- All components are in their right place
- All polarized components are in the right direction.
- Power connector and cable are properly connected.