

BASIC TROUBLESHOOTING FLOW CHART

STEPS ALREADY TAKEN BEFORE PLUGGING IN:
 - All components are in their right place
 - All polarized components are in the right direction.
 - Power connector and cable are properly connected.

